Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE8456/1
Work Order Type: Weatherization
Audit Name: Audit DE8456

CLIENT INFORMATION

Client Name: Address:

Client ID: 50005DE8456 Covington, 38019

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE **Agency Phone:** (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH **Fax:** (901) 476-5258

Agency Contact: Treadwell, Dwight Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

House built in 1967 and has several roof leaks. Attic insulation is not recommended.

Page 1 of 6

| | <i>Measure</i> 1 Re | place side door | | | Componen | ts | | | Inspected | |
|----|---------------------|--|------------|-----------|------------------|------------|----------|------------------|-----------|--|
| C | | loor is hollow core and frar door unit. | ming needs | s repai | r. Replace | with stand | dard siz | e | | |
| | | | | Estimated | | | | Actual | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 10 | Unspecified | Misc Material | Each | 1 | | | | | | |
| c | Other Detail | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| _ | | | | Measur | re Sub Total: | |] ; | Sub Total: | | |
| | Field Notes: | | | | | | 1 | | | |
| | riela Notes. | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | Measure 2 Inf | iltration Redctn | | | Componen | ıts | | | Inspected | |
| C | Comment AIR IN | IFILTRATION MEASURES | ş. | | • | | | | | |
| U | | alk all windows on the insid | | aling | | | | | | |
| | | ulk windows - 5-6-7 on the | | Jamig | | | | | | |
| | | ch holes in wall behind toil | | | | | | | | |
| | | seal plumbing penetrations | | om an | d in kitchen | under sin | k area | | | |
| | | ch Hole in ceiling over fron | | | | | | | | |
| | | ch 2 holes in ceiling in kitcl | | | | | | | | |
| | | Seal baseboards | | | | | | | | |
| | | place frameing out side do | or | | | | | | | |
| | | seal around the cielings of | | Iral cie | lings | | | | | |
| | | G | | | Estimated | ı | | Actual | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 10 | Miscellaneous | Infiltration Reduction | Each | 1 | | | | | | |
| | Supplies | | | | | | | | | |
| C | Other Detail | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Measur | re Sub Total: | | | Sub Total: | | |
| | Field Notes: | | | | | | | | | |
| | Tield Notes. | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

| Measure 3 Re | place Htg. System | | | Componen | ts 50k B | TU ver | nted wal | Inspected |
|---|--|----------------------|----------------|--------------|----------|--------|------------|-----------------|
| Comment Recon | mmend 50,000 BTU Double | e vented w | all hea | | • | s line | | |
| | | | | Estimated | <u> </u> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Heating Equipment | Space Heater - 35 kBtu/h Prop Existing, 49 - 68 kBtu/h Prop Post | Each | 1 | | | | | |
| 2 Labor | Space Heater - 35 kBtu/h Prop Existing, 49 - 68 kBtu/h Prop Post | Each | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] , | Sub Total: | |
| Field Notes: | | | | | | | | |
| ried Notes. | | | | | | | | |
| Measure 4 DV | VH Pipe Insulation | | | Componen | nts | | | Inspected |
| | VH Pipe Insulation | | | Componen | | | Actual | Inspected |
| Measure 4 DV | WH Pipe Insulation Description / Comment | Units | Qty | - | | Qty | | Inspected Total |
| Measure 4 DV Comment | · | <i>Units</i> Each | | Estimated | <u> </u> | Qty | Actual | |
| Measure 4 DV Comment # Material / Labor 1 Insulation | Description / Comment | | Qty | Estimated | <u> </u> | Qty | Actual | |
| Measure 4 DV Comment # Material / Labor 1 Insulation | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | <u> </u> | Qty | Actual | |
| Measure 4 DV Comment # Material / Labor 1 Insulation 2 Labor | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | <u> </u> | Qty | Actual | |
| Measure 4 DV Comment # Material / Labor 1 Insulation 2 Labor | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | <u> </u> | Qty | Actual | |
| Measure 4 DV Comment # Material / Labor 1 Insulation 2 Labor | Description / Comment DHW Pipe Insulation | Each Each | Qty 1 1 | Estimated | <u> </u> | | Actual | |

| Measure 5 Floo | or Ins. R-19 | | | Componen | <i>ts</i> 1120 | SF - Cr | awlspac | Inspected |
|--------------------|---|-------|---------|---------------------|----------------|---------|------------|-----------|
| | | | | Estimated | <u> </u> | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Floor Insulation - Fiberglass Batts - R-19 | SqFt | 1120 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| Measure 6 Rep | lace A/C | | | Componen Estimated | | | Actual | Inspected |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Cooling Equipmen | - | Each | 1 | | | | | |
| 2 Labor | Window A/C - | Each | 1 | | | | | |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | | | | | | |

| | II Insulation | | | Componer | ots Back, uth | Front,N | orth,So | Inspected |
|---|---|----------------------|------------------------|---------------------|------------------|---------|------------------|-----------|
| Comment | | | | Estimated | , | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Wall Insulation - Blown Cellulose - 2x4 Filled | SqFt | 978.1 | | | | | 70.01 |
| Other Detail | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measure | e Sub Total: | |] ; | Sub Total: | |
| Measure 8 Sto | rm Windows | | | Componer | Morth | Dook C | | |
| Comment | | | | Componen | ont | ,васк,ъ | South,Fr | Inspected |
| Comment | | | | Estimated | ont | Back,S | South,Fr Actual | Inspected |
| Comment # Material / Labor | Description / Comment | Units | Qty | - | ont | Qty | , | Inspected |
| # Material/Labor | | <i>Units</i> SqFt | | Estimated | ont | | Actual | |
| # Material / Labor 1 Windows | Description / Comment | | Qty | Estimated | ont | | Actual | |
| # Material / Labor 1 Windows 2 Labor | Description / Comment Storm Window | SqFt | Qty 72.89 | Estimated | ont | | Actual | |
| # Material / Labor 1 Windows 2 Labor | Description / Comment Storm Window Storm Window | SqFt SqFt Each | Qty 72.89 72.89 | Estimated | ont | | Actual | |
| # Material / Labor 1 Windows 2 Labor 3 Other | Description / Comment Storm Window Storm Window | SqFt SqFt Each | Qty 72.89 72.89 | Estimated | ont | | Actual | |
| # Material / Labor 1 Windows 2 Labor 3 Other | Description / Comment Storm Window Storm Window | SqFt SqFt Each | Qty 72.89 72.89 | Estimated | ont | | Actual | |
| # Material / Labor 1 Windows 2 Labor 3 Other | Description / Comment Storm Window Storm Window | SqFt SqFt Each | Qty 72.89 72.89 | Estimated | ont | Qty | Actual | |
| # Material / Labor 1 Windows 2 Labor 3 Other | Description / Comment Storm Window Storm Window | SqFt SqFt Each | Qty 72.89 72.89 | Estimated Unit Cost | ont | Qty | Actual Unit Cost | Total |

| Measure 9 CO Monit | or is Needed | | | Componer | nts | | ı | Inspected | |
|--|----------------------------------|------------|-----------|---------------------|--------|-----------|------------------|-----------|--|
| Comment | | | | | | | | | |
| | | | Estimated | | | | Actual | | |
| # Material / Labor Desc | cription / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| Health and Safety CO litems | monitor | Each | 1 | | | | | | |
| 2 Labor Labo | or | Hour | 1 | | | | | | |
| Other Detail | | | | | | 1 | | | |
| | | | | | |] [] | | | |
| | | | Moasur | e Sub Total: | |] []] | Sub Total: | | |
| Field Notes: | | | INCASUI | e Sub Total. | | | | | |
| Measure 10 Vapor Ba (Basemer Comment Install vapor b | nt/CrawIspace) | nd 6 inche | | | secure | | | Inspected | |
| # Material / Labor Desc | cription / Comment | Units | Qty | Estimated Unit Cost | Total | Qty | Actual Unit Cost | Total | |
| 1 Health and Safety Base | ement / crawlspace or barrier | Each | 1 | | Total | Qiy | | TOTAL | |
| 2 Labor Labo | or | Hour | 1 | | | | | | |
| Other Detail | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | Measur | e Sub Total: | |] ; | Sub Total: | | |
| Field Notes: | | | | | | | | | |
| | | | | | | | | | |